

## PRICE LIST (\$ USD) AS OF DECEMBER 4, 2013

BOX WITH ALL AVAILABLE COMPONENTS INCLUDING DRILLED HOLES FOR FOR ELECTRONICS, WATER AND GAS MANIFOLD, FULL SURROUND UHMW (5 PLATES) AND 6 PENETRATORS. THE NEW DESIGN INCORPORATES UHMW THAT COMPLETELY SURROUNDS THE INSIDE OF THE BOX. IT EXTENDS FROM THE INSIDE BOTTOM OF THE BOX TO THE INSIDE TOP. THE "TONGUE AND GROOVE" FIT USES A .002 PRESS FIT TO ELIMINATE ELECTRICAL LEAKAGE. THIS IS AN IMPORTANT ADDITION. WE CAN FIND NO SEALANT THAT WILL LAST IN THE HYDROXY FLUIDS. ALSO INCLUDES THE TOP LID FOR THE BOX.	2500.00
TOP LID FOR BOX	125.00
BOX ONLY, GLUED (NO LID)	999.00
BOX WITH UHMW SET OF 3 SLOTTED & 2 ENDS UHMW (TONGUE AND GROOVE FIT) (INCLUDES TOP LID) (No penetrators, Gas or Water Tube or fittings for same.)	1670.00
UHMW SET OF 3 SLOTTED (BOTTOM, 2 SIDES, 2 ENDS (TONGUE & GROOVE FIT) (NEW BOB BOYCE RECOMMENDATION) (SEE NOTE ON RETURNING BOX FOR FIT) (NOTE; YOU WOULD HAVE TO DRILL THE UHMW TO MATCH YOUR EXISTING BOX)	750.00
WATER FEED MANIFOLD ASSEMBLY, HAVING 100 .050 HOLES THAT INDIVIDUALLY FEED EACH CELL AND INNER "PRESSURE REDUCING" TUBE TO EQUALIZE WATER FEED AMOUNT (NOTE: You will need to install sensors to turn this device on and off – not included) (See NOTE Below)	280.00
GAS MANIFOLD ASSEMBLY. DESIGNED TO PICKUP GAS THROUGHOUT THE ENTIRE LENGTH OF THE UNIT AND FEED TO BUBBLER/ENGINE (See NOTE Below)	249.00
MAIN +/- ELECTRIC PENETRATORS FOR DIRECT HOOKUP OF ELECTRONIC SIGNALS TO THE STAINLESS PLATES. (2EA) (See Below)	149.00
SENSOR PENETRATORS (4 each) FOR WATER REFILL ON/OFF DEVICE (Note, these are only the electronic "Hookup" points, NOT the sensors themselves) (SET OF 4) FYI, THE SENSORS ARE MERELY "BARED" WIRES THAT CONTACT THE FLUID THAT COMPLETE OR BREAK CONTACT THUS TURNING ON OR OFF THE PUMP.	199.00
ALL SIX SENSORS (See Below)	299.00

### NOTES:

All "Through" fittings are equipped with "O" Rings to eliminate hydrogen leakage. Careful design procedures allow replacement of parts that may become damaged without destroying the box itself. Prices DO NOT include shipping charges.

If you have already purchased one of the "Old Style" boxes from Holdgate Enterprises, Inc., I encourage you to purchase an "Update Kit" which will include a set of five UHMW separator plates cut to .0593, giving you the new "tight fit" now recommended by Bob Boyce. It also includes the "Tongue and Groove" UHMW design.

*It is STRONGLY recommended that you return your box to me to fit and drill the holes. If not returned, you'll have to drill holes in the UHMW. This is a tricky job and I do not recommend you try it. If you return your box I will transfer and drill all the holes. A service fee of \$100. will be charged for the drilling. Only the box itself needs to be returned. Return shipping charges will also apply.*

Ed Holdgate  
Holdgate Enterprises, Inc.  
727 447 8387

31 Bohemia Circle South  
Clearwater, Florida 33767